



Photo 1. *View of dredge Tom James within Little Pass borrow area*



Photo 3. *View of main dredge pump (centrifugal) on the Tom James dredge*



Photo 2. *View of submerged cutter head from aboard Tom James*



Photo 4. *View of floating discharge pipe*



Photo 5. View of floating discharge pipe from aboard Tom James



Photo 7. Timber dock construction at end of access channel, looking north towards bay



Photo 6. View of end of floating and beginning of submerged (marked by buoys) discharge pipe to Timbalier Island



Photo 8. Access berm at appx. Sta. 170+00, looking south



Photo 9. *Pumping beach fill material (discharge pipe at Sta. 201+50), looking southwest*



Photo 11. *View of Gulf discharge pipe and shore pipe at east end of project, looking east*



Photo 10. *Pumping beach fill material (discharge pipe at Sta. 201+50), looking southwest*



Photo 12. *View of shore pipe at east end of project, looking east from Sta. 202+00*



Photo 13. *Pumping beach fill material, view of discharge pipe at Sta. 201+50, looking east*



Photo 15. *View of Timbalier shoreline and newly placed beach fill (foreground), looking west standing at appx. Sta. 200+50 on beach fill*



Photo 14. *View of Timbalier shoreline and newly placed beach fill (foreground), looking west standing at appx. Sta. 200+50 on beach fill*



Photo 16. *View of newly placed beach fill, looking east standing at appx. Sta. 200+50*



Photo 17. *Bulldozer moving newly placed beach fill material at Sta. 201+50*



Photo 19. *Pumping beach fill material at Sta. 201+50, looking southeast*



Photo 18. *Bulldozer moving newly placed beach fill material at Sta. 201+50*



Photo 20. *View of shore pipe y-valve at connection to Gulf discharge pipe at east end of project (Sta. 206+00)*



Photo 21. View of shore pipe y-valve at connection to Gulf discharge pipe at east end of project (Sta. 206+00)



Photo 23. View of shore pipe connection to Gulf discharge pipe at east end of project



Photo 22. View of side dike and back dike at east end of project (Sta. 206+00), looking north



Photo 24. View of shore pipe looking southwest from appx. Sta. 205+50



Photo 25. View of newly placed beach fill, looking west from appx. Sta. 205+50



Photo 27. View of overflow weir boxes and construction of back dike at appx. Sta. 105+00, looking northwest



Photo 26. View of overflow weir boxes and construction of back dike at appx. Sta. 105+00, looking north



Photo 28. Construction of back dike at appx. Sta. 106+00, looking northeast



Photo 29. Construction of back dike at appx. Sta. 106+00, looking north



Photo 31. View of Canal No. 19 at Sta. 93+00, standing at south end of canal at approximate location of front (Gulf side) of proposed dune looking north



Photo 30. View of Timbalier shoreline at east end of existing rock shoreline protection (Sta. 100+00), looking east



Photo 32. Sta. 93+00, standing at south end of Canal No. 19 at approximate location of front (Gulf side) of proposed dune looking east